Date:

Tuesday, 12/08/2008 9:53:08 AM

User:

Julie Lecocq

Process Sheet

Customer

: CC-DAR01 Dart Aerospace Ltd.

Job Number

: 41144

Estimate Number

P.O. Number

This Issue : 12/08/2008

: NC

: 10804

: // First Issue

: 00015

Type

S.O. No. :

: SMALL /MED FAB

Part Number

Drawing Name

: D35643 : R08-065

: D3564-3

Drawing Number

Project Number Drawing Revision

Material

Due Date : 18/08/2008 Qty:

2 Um:

Each

Written By

Prsht Rev.

Previous Run

Checked & Approved By

Comment

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

D35643



Comment: Qty.:

1.0000 Each(s)/Unit

Wearshoe

Total:

2.0000 Each(s)

Wearshoe

Original B33801

2.0

3.0

QC5

Comment: INSPECT WORK TO CURRENT STEP

PACKAGING 1

PACKAGING RESOURCE #1

INSPECT WORK TO CURRENT STEP



Comment: PACKAGING RESOURCE #1

Identify with the new batch #, and return to stock.

Location:

4.0 QC21

FINAL INSPECTION/W/O RELE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



U 08-08-19

Dart Aerospace Ltd

Dait Ac	ospaci	Liu								
W/O:	 ··· ··· ··· ···		W	ORK ORDER CH	IANGES					
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								<u> </u>		
Part No:			Fault Category: NC			R: Yes No DQA: Date:				
						QA: N	/C Close	d:	Date: _	
NCR:		V	WORK ORD	ER NON-CONFO	ORMANCE	(NCR)			
DATE		Description of NC	Corrective Action Section B				Verification		Approval	Approval
	STEP	Section A	Initial Chief Eng	Action Descri Chief Eng	ption	Sign & Date	Secti		Chief Eng	QC Inspector
										<u> </u>

NOTE: Date & initial all entries